

**CONFIDENTIAL SITE SUMMARY  
AND RECOMMENDATIONS**

The Avon Products Inc. (AVON) site is located at State Road #1, Km 26.4, in Caguas, Puerto Rico. The site consists of a small office building connected to a large warehouse, and a parking lot that surrounds roughly three-quarters of the facility. The facility was built in approximately 1950 by AVON, and the company has operated out of it since its construction. At this facility, AVON repackages finished beauty products (i.e., makeup, perfume, shoes, clothing) that are shipped in from manufacturing facilities in the United States of America. Business is conducted in the office section, while packaging and shipping takes place in the warehouse section. Manufacturing has never taken place on site and there are no known current or historic on-site waste sources.

WESTON requested files for this facility at the Puerto Rico Industrial Development Company (PRIDCO), the Environmental Protection Agency (EPA), and the Puerto Rico Environmental Quality Board (PREQB). No files of relevance were obtained, indicating that the facility does not treat, store, or generate hazardous wastes. This conclusion is supported by interviews conducted with AVON personnel and direct observations by WESTON personnel during an on-site reconnaissance.

WESTON used HRS QuickScore version 3.0.3 to evaluate the site. Based on the absence of sources or releases of hazardous substances at the facility, the waste characteristics factor value is 0 for all pathways and the site score is 0.00. Therefore, the recommendation for the site is **NO FURTHER REMEDIAL ACTION PLANNED (NFRAP)**.

DECLASSIFIED

Date: 7/13/19 Initial: *jl*

388735

